

02IND2022-01-29

Product Line: IND

Post Date: 2022-01-29

**MSD Thread Subject**

Indian Challenger with Current P0444 : Canister Purge Control Signal Open code

**MSD Post Content**

There have been some dealers that reported having a 49 state bike delivered to them that displays a current P0444 :code for a emissions canister error, when there is no canister on a 49 state bike. The canisters are used on 50 state or California legal emissions bikes. The cure is to charge the battery & attach a 5 amp or larger charger to the vehicles battery and run ECU Reprogramming/Reconfiguration and the problem should be resolved. NOTE: as of 1/29/22 I would recommend only flashing using legacy Digital Wrench NOT Digital Wrench-2 unless advised to do so by tech service at this time (1/29/22). Digital Wrench 2 is currently still causing some concerns when performing certain updates. We are working hard to correct these issues ASAP. The reflash of the ECU appears to address the population of the .P0444 :code