

**** TECHNICAL INFORMATION NOTICE ****

DATE: January 21, 2022
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Engine crank / no start in extreme cold
TIN NO. TIN-22-16-001

.....

AFFECTED VEHICLES: 2022 Outlander

PURPOSE:

Should a customer's 2022 Outlander experience a crank / no start concern that is only exhibited in severe freezing weather, please follow the process below to identify the correct course of action.

