



SERVICE BULLETIN

Classification: KS19-009B	Reference: NTB19-029B	Date: January 14, 2022
-------------------------------------	---------------------------------	----------------------------------

INTELLIGENT KEY DOES NOT WORK AFTER BATTERY REPLACEMENT

APPLIED VEHICLES: 2019 Kicks (P15) 2019 Altima (L34)
 2019 Rogue Sport (J11) 2019 Maxima (A36)
 2019 Rogue (T32) 2019 370Z Coupe & Roadster (Z34)
 2019 Murano (Z52) 2019 Titan & Titan XD (A61)
 2019 Pathfinder (R52)

This bulletin is no longer active.
 Please discard previous versions of NTB19-029.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 4, 2019	NTB19-029	Original bulletin published
February 1, 2021	NTB19-029a	Classification number updated
January 14, 2022	NTB19-029B	Bulletin no longer active