

SERVICE BULLETIN 592 - REAR SPROCKET NUT RE-TORQUE

Notice Information

Ref	20603
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor
Subject:	Service/Technical

TOL NOTICE (US) - January 24, 2022

TOL Ref. #20603 - SVC

SERVICE BULLETIN 592 - REAR SPROCKET NUT RE-TORQUE

Internal investigations have identified the rear sprocket lock nuts must be re-torqued on the models below. Dealers are requested to re-torque the lock nuts as described in the procedure below.

Triumph's warranty servers will be updated with the new codes and data and the bulletin will be saved to the TOL [Service Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action. [DOWNLOAD HERE](#)

Reminder: use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

RE-TORQUE REAR SPROCKET LOCK NUTS				
Bulletin Number	Models Affected	VIN Range		Markets Affected
592	Bonneville T100	From AX0150	To AX8715	All markets except Brazil and India
	Bonneville T120	From AX3748	To AX8997	
	Bonneville T120 Black	From AX3794	To AX9221	
	Street Scrambler	From AX3104	To AX8892	
	Street Twin	From AX3271	To AX9003	
	Thruxton RS	From AX3796	To AX9387	
	Speed Twin	From AX2845	To AX9202	
	Bonneville Bobber	From AX4245	To AX8709	
	Bonneville Speedmaster	From AX4277	To AX8985	
	Tiger Sport 660	From AW9349	To AX9217	
	Trident 660	From AX3686	To AX9241	

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Bonneville T100, Bonneville T120, Bonneville T120 Black, Bonneville Bobber, Bonneville Speedmaster, Street Scrambler, Street Twin, Thruxton RS, Speed Twin, Tiger Sport 660 and Trident 660 motorcycles in the above VIN range.

Note:

- **Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.**
- **Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.**

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.