



Bulletin No.: PIT5882A
Published date: 01/31/2022

Preliminary Information

PIT5882A History DTCs To Ignore / NO SES / NO Malfunction Indicator Lamps / NO Warning Message

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022	All	All	All	All

Involved Region or Country	North America
Condition	A technician may find any number of the following DTCs set in History. These history DTC's will NOT cause any SES, MIL's or Warning messages. The DTCs may include any number of DTCs listed in the table below.
Cause	Software Anomaly

Correction:

If any of the DTCs listed in the table below are set in History they should be ignored. There will be NO customer concerns or indication to the customer that these DTC's are set in history. If these DTCs are Current, do NOT ignore them, but diagnose as normal.

The following DTC's should be ignored if set as history:

Module	DTC#	Description
K56-Serial Data Gateway Module	U023D 00	Lost Communication with Short Range Radar Sensor - Left Front
K56-Serial Data Gateway Module	U023E 00	Lost Communication with Short Range Radar Sensor - Right Front
K56-Serial Data Gateway Module	U1126 00	Lost Communication with Short Range Radar Sensor - Left/Center Rear
K56-Serial Data Gateway Module	U1127 00	Lost Communication with Short Range Radar Sensor - Right Rear
K157-Video Processing Module	U163D 00	Lost Communication with Image Processing Module - Processor 1 on CAN Bus 3

Version History

Version	2
Modified	01/19/2022 - Created. 1/31/2022 - Updated Cause



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.