



## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
ID.4	2021-2022	All	All	All	All

### Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2066300/1	2/25/22	57-22-01TT	Original publication.

## Technical Background

ID4 vehicles are equipped with an electronic rotary latch which allows the doors to be opened with minimal effort.

When the system identifies a request to open the door, the central locking motor activates the rotary latch so that the door is opened electronically by approx. 1 cm.

The proper operation of the interior door release handle includes pulling on the interior door release handle until the “soft stop” is reached and the door pops open approximately 1 cm, at the same time pressure needs to be applied to the door for it to open. If no force is applied to the door the rotary latch will reengage and latch the door due to safety.

## Service

This is normal door release operation and no adjustment should be performed to the door latch or striker. Please advise the customer to refer to the owner manual section “Opening the door”.

## Additional Information

© 2022 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.