

SS 723-WST 2022 49X Hood Handle Mounting

Applicable Vehicles

49X vehicles

Symptoms

Hood handle mounting studs on the front of the hood may contact radiator mounted grille.

Issue

Stud length on hood handle may contact grille on certain installations.


Solution

Open hood, remove hood handle stud installations (quantity 4) and replace with part below:

23-13602-025 SCR,RND WSHRHD,HX RECSS,M6X1.0 (4)

Torq fasteners to 4.6ft/lb

4X 23-13602-025
M6 Capscrew w/Washer



Labels :

49X

Add tags



0 Kudos

Comment