

TECHNICAL TOPICS

Powertrain



AJ20-P6 P162F code Failure to restart out of eco-stop	20-22MY Defender 21-22MY Discovery
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- Customer concern will be a failure to restart after an Eco-stop. This may be interpreted as a stall, but the ignition will also turn off. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- DTC code that will be stored will be P162F. <p><u>Status:</u></p> <ul style="list-style-type: none">- PCM software is being created to resolve the issue. Timing= March (Pathfinder or OTX TBC)- Customers can continue using their vehicles if they choose, but eco stop must be disabled to prevent the risk of the issue occurring. <p>Please refer to Topix 303-07C for further diagnostic help</p>	

