

TECHNICAL TOPICS

BODY/CHASSIS



Center Air Vent Poor Airflow	22MY Discovery Sport, RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A customer may report low airflow through the center facia vents. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- This may be caused by a center air vent duct that was not installed properly. <p><u>Status:</u></p> <ul style="list-style-type: none">- Service Action N659 is being published to proactively inspect and correctly install the center air vent duct to the HVAC manifold.	

