

Subject:

**INFOTAINMENT SYSTEM CONTINUOUSLY REBOOTS NEAR
SEATTLE WASHINGTON**

Service Alert No.: SA-005/22

Last Issued : 02/09/2022

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2014-2016 Mazda3

2016 Mazda6

2016 CX-3

2016 CX-5

2016 CX-9

DESCRIPTION

Some customers may experience a continuous infotainment reboot in or near Seattle Washington.



Mazda is aware of the issue and is working on a resolution. This Service Alert will be updated with the newest repair information as it becomes available.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.