

Subject: NEW DIFFERENTIALS DO NOT COME WITH BREATHER CAPS	Service Alert No.: SA-009/22
	Last Issued : 02/18/2022

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS


2013-2022 CX-5	2016-2022 CX-9	2020-2022 CX-30
2016-2022 CX-3	2019-2022 Mazda3	

DESCRIPTION

The new AWD rear differential DOES NOT come with a breather cap on the rear of the differential, therefore a new one will need to be ordered and installed when replacing the differential.

NOTE:

- The breather threads have a sealant and locking compound that prevents it from being reused.
- Refer to GEPC for the correct part number of the Differential Breather.
- The instructions on MGSS will be updated soon to include replacing the breather when replacing the differential with a new unit.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.