



## RYKER 2022 Front Wheel Studs Inspection - 139755

### Article Detail

### Problem:

The front wheels guided studs might be broken from the factory on MY22 Rykers. These studs are required (all 3) and need to be aligned in the front brake rotor holes. If a stud is found broken, the wheel needs to be replaced.

### Solution:

At PDI, before installing the wheels on the unit, pay attention to the front wheels make sure that all studs are in good condition and not damaged.

The next picture is showing a broken stud.




If a unit is already registered, the inspection can be done at the next unit's service. Again, the inspection is visual only. No needs to remove the wheels. Simply lift up the front end and slowly turn the wheel to see the studs aligned in the front brake rotor as shown in the attached picture.

### Inspection Procedure:

Visual inspection only

[Traduire](#)



## Warranty:

Warranty Type 03 or 01 with job code 07-80 has to be used if a wheel is replaced

---

**First Published By:** Eric Fauteux on 02/01/2022

**Last Modified By:** Eric Fauteux on 02/01/2022