




Bulletin No.: PIT5891
Published date: 02/3/2022

Preliminary Information

PIT5891 2022 HUMMER EV Forward Collision System Unavailable Message displayed in the Drivers Information Center.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022	All	All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may experience a "Forward Collision System Unavailable" message along with a amber collision icon illuminated when the vehicle is in Service mode (Ignition on Propulsion Off)</p>  <p>Note: Service Mode is achieved with the vehicle off, and the brake pedal not applied, then pressing and holding the POWER button for more than five seconds. This will place the vehicle in Service Mode.</p>
Cause	The forward collision system is not available in Service Mode.

Correction:

Please do not attempt any repairs on the vehicle as this is a normal characteristic of the vehicle at this time.

Note: If the message remains on after starting the vehicle, please review for DTC's and follow SI diagnostics for further direction.

Version History

Version	1
Modified	02/03/2022 - Created on.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.