

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS6086  
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 17, 2022

Subject: Stop Delivery Order for N222363820  
Driver's Side Rear Wheel Liner Missing

Models: 2022 Chevrolet Blazer

To: Select General Motors Dealers in Michigan and Ohio Only

Attn: Dealer Principal, Sales/Service/Parts Managers

**STOP DELIVERY ORDER**

Effective immediately, stop the delivery on certain 2022 model year Chevrolet Blazer vehicles in new vehicle inventory. Attached is a list of the involved BACs and the associated VINs.

It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification until the defect is remedied.

Important: Parts will be shipped and are expected to arrive to your dealership in the near future. We will be communicating the driver's side rear wheel liner repair procedure, including the labor codes and labor time required to you soon.

Until further instructions are received, these involved vehicles that are in your possession must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration purposes or any other dealer use.

The Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system will be updated on March 17, 2022.

Until the recall bulletin is released, the Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system will display "Open" under Release Date and "Stop Delivery" under Status. This means the required parts are not available and you should not attempt to perform any repairs.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS