

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6092
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 21, 2022

Subject: Stop Delivery Order for N222363820
Driver's Side Rear Wheel Liner Missing

Models: 2022 Chevrolet Blazer

To: James Martin Chevrolet

Attn: Service and Parts Managers

STOP DELIVERY ORDER

Effective immediately, stop the delivery on one 2022 model year Chevrolet Blazer vehicle in new vehicle inventory. Below is the associated VIN.

3GNKBHR47NS147723

It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification until the defect is remedied.

Important: Parts will be shipped and are expected to arrive to your dealership in the near future. We will be communicating the driver's side rear wheel liner repair procedure, including the labor codes and labor time required to you soon.

Until further instructions are received, these involved vehicles that are in your possession must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration purposes or any other dealer use.

The Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system was updated on March 17, 2022.

Until the recall bulletin is released, the Investigate Vehicle History (IVH) screen in the Global Warranty Management (GWM) system will display "Open" under Release Date and "Stop Delivery" under Status. This means the required parts are not available and you should not attempt to perform any repairs.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS