Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

DOPPLER RADAR SIMULATOR (SPECIAL SERVICE TOOL)
LOANER PROCESS

Last Issued: 03/25/2022

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previous TSBs:	Issued Dates:
00-002/20	10/22/2020
00-004/18	08/10/18
00-003/17	12/22/17
00-005/16	08/26/16
00-001/15	08/06/15

APPLICABLE MODEL(S)/VINS

2016-2021 CX-3

2016-2022 MX-5

DESCRIPTION

In support of the new Mazda MX-5 and CX-3, Mazda will make available for loan on an "as-needed" basis, a Special Service Tool (SST) to allow for the radar aiming of the blind spot monitoring (BSM) system. The BSM radar aiming is performed whenever the BSM control module, the BSM bracket or the rear bumper is replaced.

Part Number	Description	Availability
49G0-67-0A0L	Doppler Radar Simulator Tool (Loaner)	The tool is available for loan by contact ing DAG at (877)727-6626, option 2. NOTE: Dealer will be charged a deposi t and reimbursed when the tool is return ed.
		Doppler tools are also available for pur chase through the Mazda Tool Program .

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Bulletin No.: 00-003/22 Last Issued : 03/25/2022

SHIPPING INFORMATION

IMPORTANT:

- The tool will be delivered with your Dedicated Parts Delivery Service (DDS).
- Ensure all related repairs are completed prior to the tool's arrival at the dealer.
- Dealer is responsible for packaging and returning the tool in the same condition as it was delivered.

SPECIAL SERVICE TOOL (SST) AND USAGE



Page 2 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.