


B-pillar trim seal on rear doors peeling

Topic number	LI72.12-P-074542
Version	1
Function group	72.12 - Rear door
Date	3/10/22
Validity	MODEL 177 up to and including production date: November 2021.
Reason for change	

Complaint

The seal on the B-pillar trim of the rear doors may be peeling on upper area, see picture 1.

Attachments

File	Description
Bild 1.jpg	
	

XENTRY TIPS

Cause

The part may exhibit this behavior under normal use.

Remedy

Replace B-pillar trim through optimized parts.

WIS-References		
Document number	Title	Note
AR72.12-P-0001MFA	Remove/install sealing for side window at rear door	Step 7

Symptoms
Body > Door/Flap > Door > Door > Seal cracked/torn
Body > Door/Flap > Door > Trim > Loose

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A177732010028			LEFT REAR DOOR TRIM	1		X
A177732020028			RIGHT REAR DOOR TRIM	1		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			73A0407	
			73N0407	