



Mack MMD Models - Coolant Hose Obstructs Access To Oil Filter



Affected vehicles will have a straight fitting for the expansion tank hose installed where the lower radiator hose connects to the engine.

If the oil filter is found to be blocked by the hose, replace the straight fitting with a 45 degree fitting, part number 20907677.

- Ensure the fitting is oriented as shown in the image below.
- Refer to Impact for proper tools and procedures for draining coolant.





Tags

- [mack](#)
- [mmd](#)
- [oil filter blocked](#)
- [oil filter](#)
- [expansion tank hose](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article



Live UI