

# Customer Notification



DEPARTMENT OF COMPLIANCE  
VEHICLE SAFETY AND RECALL MANAGEMENT  
BUILDING 11  
423 N MAIN ST  
MIDDLEBURY, INDIANA 46540-9218

Customer Notification: 51-1499

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

<<OWNER NAME/DEALERNAME>>  
<<ADDRESS>>  
<<CITY>>, <<ST>> <<ZIP-XXX>>

March 2022

This Notice applies to your vehicle VIN listed above.

Dear Forest River Customer:

Forest River is alerting you to a Ford Recall 22S08, NHTSA ID 22V089 involving a single Forester 2501 TSF Class C Motorhome. Please see the information below, which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

### **WHAT IS THE ISSUE?**

The power steering pressure line in your vehicle may be inadequately connected to the brake Hydro boost unit, which may result in a leak or sudden loss of power steering fluid. Sudden loss of power steering fluid may result in a loss of power steering assist, requiring increased steering effort, and loss of power brake assist, requiring increased force on the pedal to brake, potentially resulting in increased stopping distance. A sudden loss of power steering assist and power brake assist increases the risk of a crash.

### **OWNERS AND DEALERS: WHAT SHOULD YOU DO?**

Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River  
Office of Corporate Compliance



Ford Motor Company  
 Ford Customer Service Division  
 P. O. Box 1904  
 Dearborn, Michigan 48121-1904



771533014664

A/62793/015699/15699



FOREST RIVER  
 900 COUNTY ROAD 1 N  
 ELKHART, IN 46514-8992

March 2022

**\*\*\* IMPORTANT SAFETY RECALL \*\*\***

**Safety Recall Notice 22S08 / NHTSA Recall 22V089**

2021 E-450 Econoline

Your Vehicle Identification Number (VIN): 1FDXE4FN6MDC16715

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

**What is the issue?**

The power steering pressure line in your vehicle may be inadequately connected to the brake Hydroboost unit, which may result in a leak or sudden loss of power steering fluid.

**What is the risk?**

Sudden loss of power steering fluid may result in a loss of power steering assist, requiring increased steering effort, and loss of power brake assist, requiring increased force on the pedal to brake, potentially resulting in increased stopping distance. A sudden loss of power steering assist and power brake assist increases the risk of a crash.

**What will Ford and your dealer do?**

Ford Motor Company has authorized your dealer to inspect the power steering pressure lines at the quick-connect fitting and if necessary, replace the lines, free of charge (parts and labor).

**How long will it take?**

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time. Additional time may be required to allow the engine to cool prior to performing this repair. In addition, your vehicle will require an inspection to determine if parts need to be ordered.

**What should you do?**

Please call your dealer without delay and request a service date for Recall 22S08. Provide the dealer with your VIN, which is printed near your name at the beginning of this letter.

Ford has not issued instructions to stop driving your vehicle under this safety recall. You should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. You can continue to safely drive your vehicle.

If you do not already have a servicing dealer, you can access [ford.com/support](https://ford.com/support) for dealer addresses, maps, and driving instructions.

Ford Motor Company wants you to have this safety recall completed on your vehicle. The vehicle owner is responsible for making arrangements to have the work completed. Ford Motor Company can deny coverage for any vehicle damage that may result from the failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

**Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.**

**What should you do?  
(continued)**

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play. In addition there are other features such as reserving parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

**COVID-19  
(CORONAVIRUS)**

Ford dealerships have implemented enhanced protocols to ensure both your safety and the safety of dealership employees. This includes specific procedures for cleaning and disinfecting customer vehicles before and after each vehicle is serviced. In most places, vehicle service has been deemed a critical service. Please contact your local dealer to confirm current service hours. For more information on how Ford and your local dealer are working hard to keep you on the road during these challenging times, please visit [ford.com/support](http://ford.com/support).

**Do you need a rental vehicle?**

If your dealer determines that power steering line replacement is required and needs your vehicle overnight, your dealer is authorized to provide a rental vehicle for your personal transportation at no charge (except for fuel and insurance) while your vehicle is at the dealership for repairs. Please see your dealer for guidelines and limitations.

**Have you previously paid for this repair?**

If you have previously paid for a repair that addresses the issue described in this letter, you still need to have this recall performed to ensure the correct parts were used.

You may be eligible for a refund of previously paid repairs. Refunds will only be provided for service related to power steering line replacement due to the quick-connect being disconnected. To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer.

Refund requests may also be sent directly to Ford Motor Company. To request your refund from Ford, send the refund request with all required documentation, including your original repair receipt (no photocopies), to Ford Motor Company at P.O. Box 6251, Dearborn, Michigan 48121-6251. Refund requests mailed to this address may take up to 60 days to process. Your original receipt will be returned to you.

Detailed information regarding eligibility for Ford's reimbursement program and documentation requirements may be obtained by contacting the Ford Customer Relationship Center at 1-866-436-7332.

**What if you no longer own this vehicle?**

If you no longer own this vehicle, and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

**Can we assist you further?**

If you have difficulties getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

RETAIL OWNERS: If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332** and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

For the hearing impaired call 1-800-232-5952 (TDD). Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

FLEET OWNERS: If you have questions or concerns, please contact our **Fleet Customer Information Center at 1-800-34-FLEET**, choose Option #3, and one of our representatives will be happy to assist you. If you wish to contact us through the Internet, our address is: [fleet.ford.com](http://fleet.ford.com).

Representatives are available Monday through Friday: 8:00AM - 8:00PM (Eastern Time).

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to [safercar.gov](http://safercar.gov). Reference NHTSA Safety Recall 22V089.

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company  
 División de Servicio al Cliente de Ford  
 P. O. Box 1904  
 Dearborn, Michigan 48121



771533014664

A/62795/015699/15699



FOREST RIVER  
 900 COUNTY ROAD 1 N  
 ELKHART, IN 46514-8992

Marzo de 2022

**\*\*\* CAMPAÑA DE SEGURIDAD IMPORTANTE \*\*\***

**Aviso de campaña de seguridad 22S08 / Campaña 22V089 de la NHTSA**

2021 E-450 Econoline

Número de identificación del vehículo (VIN): 1FDXE4FN6MDC16715

Este aviso se le envía de acuerdo con la Ley Nacional de Seguridad y Tránsito de Vehículos de los EE. UU. Ford Motor Company ha determinado que su vehículo presenta un defecto relacionado con la seguridad del motor, con el VIN que aparece más arriba.

Lamentamos esta situación y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

**¿Cuál es el problema?**

La tubería de presión de la dirección hidráulica de su vehículo podría estar conectada de forma inadecuada a la unidad de HydroBoost del freno, lo cual podría ocasionar una fuga o una pérdida repentina de fluido de la dirección hidráulica.

**¿Qué riesgo existe?**

Una pérdida repentina del fluido de la dirección hidráulica podría generar una pérdida de la asistencia de la dirección hidráulica, lo cual implica un mayor esfuerzo en la dirección y una pérdida de la asistencia de frenado eléctrico, lo que se traduce en una mayor fuerza sobre el pedal del freno; esto potencialmente podría traducirse en una mayor distancia de frenado. Una pérdida repentina de la asistencia de la dirección hidráulica y de la asistencia de frenado eléctrico aumenta el riesgo de choque.

**¿Qué medidas adoptarán Ford y su distribuidor?**

Ford Motor Company ha autorizado a su distribuidor a inspeccionar las tuberías de presión de la dirección hidráulica en la conexión rápida y, si fuera necesario, a reemplazar dichas tuberías, sin costo alguno (piezas y mano de obra).

**¿Cuánto tiempo tomará?**

El tiempo necesario para reparar será menos de medio día. Sin embargo, debido a los requisitos de planificación de servicio, es posible que su distribuidor tarde un poco más. Es posible que se necesite más tiempo para permitir que el motor se enfríe antes de realizar esta reparación. Además, se realizará una inspección del vehículo para determinar si se deben solicitar piezas.

**¿Qué debe hacer?**

Llame de inmediato al distribuidor y solicite una cita de servicio para realizar la campaña 22S08. Proporcione el VIN a su distribuidor, el cual está impreso debajo de sus datos al comienzo de esta carta.

Para esta campaña de seguridad, Ford no ha emitido instrucciones de no manejar el vehículo. Deberá ponerse en contacto con su distribuidor a fin de programar una cita para solucionar este problema lo más pronto posible. Puede continuar manejando su vehículo con seguridad.

Si aún no tiene un distribuidor para realizar el servicio, puede acceder a [ford.com/support](http://ford.com/support) para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

Ford Motor Company le recomienda realizar esta campaña de seguridad en su vehículo. El propietario del vehículo es responsable de realizar los arreglos necesarios para llevar a cabo el trabajo. Ford Motor Company puede negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

**Tenga presente que: La ley federal exige que los arrendadores de vehículos que reciban este aviso de campaña envíen una copia del mismo al arrendatario en un plazo de diez días.**

**¿Qué debe hacer?  
(continuación)**

NOTA: Puede recibir información sobre las campañas y los programas de satisfacción del cliente a través de la aplicación FordPass. La aplicación se puede descargar a través de App Store o Google Play. Adicionalmente, existen otras funciones como reserva de estacionamientos en determinados lugares, además de control de ciertas funciones en el vehículo (bloqueo o desbloqueo de puertas, arranque remoto) si así está equipado para permitir el control.

**COVID-19  
(CORONAVIRUS)**

Los distribuidores Ford han implementado protocolos mejorados con el fin de asegurar tanto su seguridad como la de los empleados de los diferentes distribuidores. Esto incluye procedimientos específicos de limpieza y desinfección antes y después de realizar servicio en cada uno de los vehículos de nuestros clientes. En la mayoría de los lugares, la atención de vehículos se ha considerado un servicio esencial. Póngase en contacto con su distribuidor local para confirmar las horas de servicio actuales. Para obtener más información sobre cómo Ford y su distribuidor local están trabajando arduamente para mantenerlo en las calles durante estos tiempos difíciles, visite [ford.com/support](http://ford.com/support).

**¿Necesita un  
vehículo de alquiler?**

Si su distribuidor determina que es necesario efectuar el reemplazo de la tubería de la dirección hidráulica y el vehículo debe permanecer en las instalaciones durante la noche, el distribuidor está autorizado a ofrecerle un vehículo de alquiler para su transporte personal sin costo (excepto combustible y seguro) mientras su vehículo se encuentre en reparación. Comuníquese con su distribuidor para conocer las pautas y limitaciones.

**¿Ha pagado  
anteriormente por  
esta reparación?**

Si anteriormente ha pagado por la reparación que aborda el problema descrito en esta carta, igualmente deberá realizar esta campaña de seguridad a fin de asegurarse de que se hayan utilizado las piezas correctas.

Es posible que cumpla con los requisitos para recibir un reembolso por las reparaciones pagadas previamente. Los reembolsos solo se otorgarán por servicios relacionados con el reemplazo de la tubería de la dirección hidráulica debido a la desconexión de la conexión rápida. Para comprobar si cumple con los requisitos y agilizar el reembolso, proporcione el recibo de pago original a su distribuidor.

También puede enviar las solicitudes de reembolso directamente a Ford Motor Company. Para solicitar un reembolso a Ford, envíe la solicitud con toda la documentación requerida, incluido el recibo original de la reparación (no envíe fotocopias), a Ford Motor Company, P.O. Box 6251, Dearborn, Michigan 48121-6251. El procesamiento de las solicitudes de reembolso enviadas a esta dirección puede tardar hasta 60 días. Su recibo original le será regresado.

Comuníquese con el Centro de Relación con Clientes al 1-866-436-7332 para obtener información detallada relacionada con el programa de reembolso de Ford y los requisitos de documentación.

**¿Qué pasa si usted  
ya no es el  
propietario del  
vehículo?**

Si usted ya no es el propietario del vehículo y tiene la dirección del propietario actual, le solicitamos que le reenvíe esta carta.

Usted recibió este aviso porque las regulaciones del gobierno exigen el envío de notificaciones al propietario conocido más reciente del registro. Nuestros registros se basan principalmente en datos estatales y de propiedad, que indican que usted es el propietario actual del vehículo.

**¿Podemos hacer  
algo más por usted?**

Si tiene problemas para reparar de inmediato su vehículo y sin costo alguno, comuníquese con el Gerente de Servicio de su distribuidor para solicitar ayuda.

**PROPIETARIOS MINORISTAS:** Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332** y uno de nuestros representantes con gusto lo atenderá. Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). Los representantes atienden de lunes a viernes, de 8:00 a.m. a 8:00 p.m. (hora del este).

**PROPIETARIOS DE FLOTAS:** Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Información a Clientes de flotas al 1-800-34-FLEET**, elija la opción n.º 3 y uno de nuestros representantes con gusto lo atenderá. Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: [fleet.ford.com](http://fleet.ford.com).

Los representantes atienden de lunes a viernes, de 8:00 a.m. a 8:00 p.m. (hora del este).

Si aun así tiene problemas para reparar su vehículo en un periodo de tiempo razonable o sin costo, puede escribir al Administrador de National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590, llamar a la Línea directa de seguridad vehicular al 1-888-327-4236 (TTY: 1-800-424-9153) o visitar [safercar.gov](http://safercar.gov). Referencia: Campaña de seguridad 22V089 de la NHTSA.

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente