

Subject		Market	
<b>Engine Oil Pan Leak</b>		<b>USA</b>	
Service Category	Section		
Engine/Hybrid System	Lubrication		
Applicability			
2017-2022 Highlander 2017-2020 Sienna			

**APPLICABLE VEHICLES**

2017-2022	Highlander	2017-2020	Sienna
-----------	------------	-----------	--------

**CONDITION**

Some 2017-2022 Highlander, and 2017-2020 Sienna vehicles may experience an engine oil leak condition from the No.2 Oil pan. This issue is currently under investigation. Please take detailed pictures of the oil pan leak condition before repair.

**RECOMMENDATIONS**

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. Please take a detailed picture of the untouched oil pan leak condition and attach photos to the TAS case. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**LINK REFERENCES**

This Tech Tip does not contain any link references