

Parts Bulletin

TITLE:

**Service Action S10138: Cert Reload
Model Year 2021-2022 Polestar 2**

**GROUP:
30**

**NO:
S10138**

**CAR MARKET:
United States and Canada**

**REVISIONS:
Updated the number of
affected vehicles**

**ISSUE DATE:
2021-11-19**

**STATUS DATE:
2022-03-24**

Page 1 of 1

Reference Bulletin: QB S10138

Polestar Automotive USA, Inc. on behalf of Polestar Performance AB, have decided to launch Service Action S10138 on certain model year 2021-2022 Polestar 2 vehicles.

Polestar investigations have identified an issue with digital certificates which renders the car unable to accept an Over-The-Air update (a manual update at retailers is still possible). This may lead to the customer losing connectivity between the vehicle and the Polestar app.

UPDATED - A total of 183 U.S. and 18 Canadian vehicles are eligible for this service action.

The following part numbers apply:

Part Number	Description	Qty
32292674	Total Upgrade PS 2	1
32264753	Change Market Certificate	1

Note: It's important to do a total upgrade BEFORE downloading a new certificate.