



# SERVICE BULLETIN!

SERVICE BULLETIN #1156  
April 4, 2022

Dear Morbark Dealer:

Morbark strives to maintain continuous improvement of our product lines even after they have entered the field. As noted in previous monthly Dealer Communication's, we have been working closely with our Ford gasoline engine supplier to improve the Ford 6.2 liter, 165-HP gasoline engine package to address field relayed concerns of reducing engine and exhaust overheating. A Post Production Modification (PPM) is being released containing instructions and part numbers for the updates needed for this engine package. Please find PPM-103 attached to this bulletin and Service Bulletin Communication email.

New machines leaving the factory already have the updates completed. Please refer to the chart below and the PPM to determine which models and serial numbers are affected. Over the past year we have made changes to this engine package, so not all updates will be required on every machine built with a Ford 6.2 liter, 165-HP gasoline engine. The PPM explains how to identify what updates will be needed on each machine.

**Please refer to the quick reference chart below for the potentially affected machines:**

Model	Serial Numbers Effected	Part Numbers
EB1821	Pre – 26469	(1) Rear Panel, P/N 40780-451
EB 1922	Pre- 52783	(1) Top Panel, P/N 30501-451
EB2131	All with Ford Engines	(3) Exhaust Clamp, P/N 29232-598 (1) Fan, Puller, P/N 29119-103 (1) Radiator Debris Screen, P/N 40861-451

Service Bulletins can be accessed within the Morbark Dealer Intranet under the Service tab. Should you have any questions, please contact Morbark's Technical Service Department at (800) 255-8839.