



Service Bulletin


Bulletin No.: 21-NA-212

Date: April, 2022

INFORMATION

Subject: Information on Power Front Seat Adjuster Track Service Part Availability Separate from Complete Seat Cushion Frame Assembly

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016	—	—	All	All
	Malibu	2017	2022				
Cadillac	XT4	2019	2022				

Involved Region or Country	North America, Chile, Europe, Israel, Middle East, Egypt, GM Korea Company, Cadillac Korea (South Korea)
Information	If there are issues with fore/aft movement, binding or other conditions of the power front seat adjuster track, and the diagnosis leads to front seat adjuster track replacement, the front seat adjuster track has been released as a service part (no longer serviced by the complete seat cushion frame assembly).
Correction	<p>Note: Do not replace the complete seat cushion frame assembly for a seat track movement condition.</p> <div style="text-align: center;">  </div> <p style="text-align: right; font-size: small;">5902829</p> <p>Caution: To remove the new power front seat adjuster track from the shipping container, lift it up with one hand on each track. Do not lift the power front seat adjuster track by holding the bridge; it may cause damage to the material.</p>



5749025

Note: The "TRACK, F/SEAT ADJR" part numbers can be found in the electronic parts catalog (EPC).

Replace the front seat adjuster track (2). Refer to *Front Seat Adjuster Track Replacement* in SI.

Version	2
Modified	Released September 17, 2021 April 25, 2022 – Reworded second Note in Correction.

