



## STAR ONLINE PUBLICATION



**Case Number:** S2223000016

**Release Date:** March 2022

**Symptom/Vehicle Issue:** Bump In Center Of Front Fascia Bumper



**Discussion:** Bulge on front fascia due to night vision washer hose being trapped between fascia and grille. This would only be applicable vehicles equipped with night vision (sales code XNT). To correct the condition the fascia must be removed and

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**



## STAR ONLINE PUBLICATION



washer hose routing corrected. Refer to 13 - Frame and Bumpers / Bumpers / FASCIA, Front / Removal and Installation.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**