

# Technical Journal

TITLE:

**SiriusXM Song/Artist Information does not Update on Screen**

<b>REF NO:</b> TJ 36140.1.2	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2022-03-28	<b>STATUS DATE:</b> 2022-04-01
<b>FUNC GROUP:</b> 3900	<b>FUNC DESC:</b> Media, navigation and communication	Page 1 of 2	

“Right first time in Time”

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

**DESCRIPTION:**

*\*Updated repair information under Service*

*\* Model type 539 added*

When listening to SiriusXM radio, the customer may experience the song/artist information not updating on the center screen when changing channels or when the song changes.

**CSC** Customer Symptom Codes

Code	Description
XD	Audio other/Audio unit display does not work
2P	Satellite radio/Does not work

**DTC** Diagnostic Trouble Codes

**Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
236							2022-2022		-	202123-999952
238							2022-2022		-	202123-999952
246							2022-2022		-	202123-999952

## Technical Journal 36140.1.2

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2021-2022		-	202037-999952
539							2022-2022		-	202139-999952

### **SERVICE:**

\* This concern is resolved with the latest IHU software (released 3/28/2022). To install it, download a Total Upgrade per TJ 31543.

### **Warranty claim info:**

See TJ 31543

### **VEHICLE REPORT:**

\*Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report " and sub concern area "Support needed", use function group 3900.