



Service Bulletin

Bulletin No.: 22-NA-102

Date: May, 2022

INFORMATION

Subject: Information on Front Door Trim Panel Design Change with Matching Door Design Change

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	HUMMER EV	2022	2022				

Involved Region or Country	United States
-----------------------------------	---------------

Information

A design change occurred mid model year that effects how the front door trim panel attaches to the front door inner sheet metal. This is a coordinated change and the correct mating parts are required to allow proper attachment of the door trim panel to the door sheet metal.

When replacing either the front door trim panel and/or the front door assembly, care must be taken to ensure the correct Part Number's are used for the repair.

If installing an updated door trim panel, you must also ensure the door is of the updated design to ensure the attachment point matches.

Service Information has been updated to include both designs as shown below.

Front Side Door Trim Removal and Installation (With Front Side Door Trim Bolt Cap)

Front Side Door Trim Removal and Installation (Without Front Side Door Trim Bolt Cap)

Front Side Door Trim Replacement (With Front Side Door Trim Bolt Cap)

Front Side Door Trim Replacement (Without Front Side Door Trim Bolt Cap)

Old Design without Trim Bolt Cap



6074919



6074921



6074922

New Design with Trim Bolt Cap



6074920

In the event that the older designed parts are no longer available, you will need to replace either the trim panel or door with the newer designed parts to ensure the attachment features match.

Version	1
Modified	Released May 17, 2022

