

Subject: Engineering Information - Transmission Fluid Leak Coming from the Front of the Transmission

This PI has been revised to end the need for information from the field. Please discard PIE0691.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD/3500HD	2022	2022	—	—	Equipped with 6.6L Engine (RPO L5P)	Equipped with 10 SPD Transmission (RPOs MGM, MGU)
GMC	Sierra 2500HD/3500HD						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released April 19, 2022 Revised May 23, 2022 – Ended the need for further information from the field.