

Subject: Engineering Information - Request for Pictures On Water Leak Issues at Sunroof Window - Rear

This PI has been revised to end the need for information from the field. Please discard PIE0581B.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2021	2022	-	-	-	-
Chevrolet	Traverse						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	4
Modified	Released August 17, 2020 Revised December 14, 2020 – Added 2021 Model Year and update the Correction. Revised December 03, 2021 – Revised to remove 2020 Model Year and add 2022 Model Year Revised January 25, 2022 – Ended the need for further information from the field.