

GROUP	MODEL
Emissions Service	2020MY
Campaign	Sportage (QL)
	w/2.0L T-GDI
NUMBER	DATE
SC222 (Rev 1, 06/16/2022)	April 2022

VOLUNTARY EMISSIONS SERVICE CAMPAIGN

SUBJECT:

VEHICLE EMISSION CONTROL INFORMATION (VECI) LABEL REPLACEMENT (SC222)

NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This bulletin provides information to replace the Vehicle Emission Control Information (VECI) label on some 2020MY Sportage (QL) vehicles with 2.0L T-GDI engines produced from December 19, 2018 through May 13, 2020. An incorrect VECI label was installed during production of these vehicles. The VECI label is extremely important when performing maintenance, emissions inspection, or ordering engine and engine management related parts. It also contains the code that tells a testing facility which test to perform to ensure the vehicle is tested to the correct emission standard. The U.S. Environmental Protection Agency and California Air Resources Board consider the under hood VECI label an integral part of state emission testing. If the VECI label is incorrect, the vehicle may fail the emission testing, even if it meets applicable emissions standards. Follow the procedure outlined in this publication to affix the correct VECI label. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



Updated VECI Label (FWD)



Updated VECI Label (AWD)

■ NOTICE

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service \rightarrow Warranty Coverage \rightarrow Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.

SUBJECT:


VEHICLE EMISSION CONTROL INFORMATION (VECI) LABEL REPLACEMENT (SC222)

Replacement Procedure:

 Open the hood and locate the existing Vehicle Emission Control Information (VECI) label.



2. Select the new VECI label with the **correct** EVAP information for FWD or AWD, as shown below.



3. Clean the surface of the incorrect VECI label with an alcohol wipe or an equivalent cleaner.



Failure to clean the surface will prevent the new label from adhering properly.

4. Carefully affix the new provided VECI label over the old VECI label, ensuring complete coverage of the old label with the new one.

(i) IMPORTANT

Ensure the correct label (FWD or AWD) is affixed to the vehicle. Refer to Parts Information for proper part number.



SUBJECT:

VEHICLE EMISSION CONTROL INFORMATION (VECI) LABEL REPLACEMENT (SC222)

AFFECTED VEHICLE RANGE:

Model	Production Date Range		
Sportage (QL)	December 19, 2018 to May 13, 2020		

REQUIRED PART:

Part Name	Part Number	Figure		Detail
Vehicle Emission Control Information (VECI) Label	35417 2G953QQK*	Conforms to regulations: USERN: 13870 LDT2 OBD: CAI Fuel: Gasoline California: LCW III LLEVTO LDT2 OBD: CAI Fuel: Gasoline California: LCW III LLEVTO LDT2 OBD: CAI Fuel: Gasoline No edjournments needed: ODE: LOWING OBD: CAI Fuel: Casoline No edjournments needed: ODE: LOWING OBD: CAI Fuel: Casoline AND STATE OBD: CAI Fuel: Casoline No edjournments needed: ODE: LOWING OBD: CAI Fuel: Casoline AND STATE OBD: CAI Fuel: Casoline No edjournments needed: ODE: LOWING OBD: CAI Fuel: Casoline AND STATE OBD: CAI Fuel: Casoline No edjournments needed: ODE: LOWING OBD: CAI Fuel: Casoline AND STATE OBD: CAI Fuel: Casoline DE STATE OBD: CAI Fuel: Casoline AND STATE OBD: CAI Fuel: Casoline DE STATE OBD: CAI	1	FWD
	35417 2G963QQK*	VEH.CL. EMISSION CONTROL INFORMATION Conforms to regulations: 2000 MV U.S.FIN: 1879 LDT2 Californis: LEVI IIU LEVPO LDT2 OBS: CAII Fuel: Castoline Grass: LANXITCO-RGS Evas: LANXITC	1	AWD

*Note: Please be aware that customers of the affected vehicles will be receiving the corrected VECI labels with the Campaign letter so they can apply them to their own vehicle; however, customers will also be informed that they can request to have their dealer affix them if preferred. DO NOT order labels for stocking purposes.

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
QL (EMP)		35417 2G953 35417		(SC222)	210172R0	0.2 M/H	35417	- 1
(FWD)	R		0				2G953QQK	
QL							35417	
(AWD)		2G963		21111001011 20001			2G963QQK	
QL (ALL)			(SC222)					
		R 35417 2G963 0		Application of Updated	210172R1	0.2 M/H		
				Emission Label				
	D		(Customer provided label)			N/A	0	
	IX.			(SC222)			IN/A	
			Dealer Verified Updated	210172R2	0.1			
				Emission Label	210172112	M/H		
			(Customer installed label)					

Note: Refer to Warranty Bulletin 2022-21 for claim submission procedures.



VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SC222 when accessing the WebDCS system.

