

Subject		Market
<b>Engine Oil Leak from No. 2 Oil Pan for F and G Serial Number Engines Leak from No. 2 Oil Pan</b>		USA
Service Category	Section	
Engine/Hybrid System	Lubrication	
Applicability		
2017-2022 RX350		

**APPLICABLE VEHICLES**

2017-2022	RX350
-----------	-------

**CONDITION**

Some 17-22MY RX350 vehicles with **engine serial numbers that start with F or G**, may experience an engine oil leak condition from the No.2 Oil pan. This issue is currently under investigation. Please take detailed pictures of the location of the oil pan leak condition before repair.

If the condition is on applicable vehicles with engine serial numbers that do not start with F or G, disregard and proceed with normal repair.

**RECOMMENDATIONS**

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. Please take a detailed picture of the location of the untouched oil pan leak condition and attach photos to the TAS case. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**LINK REFERENCES**

This Tech Tip does not contain any link references