



Technical Service Bulletin

47 Brake Servo Unit is noisy when pressing the brake pedal - Q5

47 22 13 2067321/1 June 14, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, and SQ5	2018 – 2020	All	Not applicable
Q5, SQ5, Q5 Sportback, and SQ5 Sportback	2021	00001 – 204966	

Condition

Customer states:

- Squeak noises can be heard when pressing the brake pedal.

Workshop findings:

- The noise can be reproduced and is coming from the Brake Servo Unit (Brake Booster).

Technical Background

The noises are coming from the brake servo unit rubber boot.



NOTE:

This bulletin does **not** include PHEV vehicles.

Production Solution



Technical Service Bulletin

Improved rubber boot was introduced gradually in 1st Quarter 2021.

Service

If noises are identified when pressing the brake pedal, proceed as follows:

- Record an audio file of the complaint.
- Attach the audio file in the DOC-IT database (Include VIN Number in the file).
- Replace Brake Servo Unit according to:

ELSA>>Repair Manual>>Chassis>>Brake System>>47 Hydraulic Components>>Brake Booster/Brake Master Cylinder>>Brake Booster Removing/Installing.



NOTE:

Replaced Components without audio files uploaded to DOC-IT will be debited!

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.		
Service Number:	4770		
Damage Code:	0020		
Labor Operations:	Brake servo unit replace	4770 1900	See SRT
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic



Technical Service Bulletin

			protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2067321/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Brake Servo Unit (Brake Booster)	See ETKA/ELSA
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (**2067321**) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or



Technical Service Bulletin

otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.