

GPOP - Issue Review System

Part Number: 6WN54LT5A\$, 6WN54TU6A\$, 6WN55BD3A\$, 6WN55HL1A\$

Part Description: INSTRUMENT PANEL, Base Panel (Top Pad, Leather)

Issue If you are replacing a leather instrument panel top pad for any leather defects
Description: (bubbling, delamination, wrinkling, etc.), please contact
FCA Redacted Content.

If no response in 15 minutes, proceed with repair.

Please send pictures of the leather defect to FCA Redacted Content.