

GPOP - Issue Review System

Part Number: 68395986A\$

Part Description: HOUSING, Air Inlet

Issue Description: For concern of whistle noise from right side of vehicle at 45+mph, please contact one of the following:

FCA Redacted Content

If no response in 15 minutes, proceed with repair.

Please investigate HVAC to firewall connection between the fresh/recirculation housing and the firewall. Identify any obstructions that could be causing a gap.

Loosen HVAC housing and retorque and/or install additional packing 68396044A\$ at the air inlet housing to the firewall to eliminate any potential gap.

Please email pictures of the issue with results to FCA Redacted Content.