

GPOP - Issue Review System

Part Number: 68298334A\$, 68298468A\$, 68607452A\$, 68507366A\$, 68483780A\$, 68384225A\$, 68384226A\$, 68576492A\$, 56046503A\$

Part Description: Rain Sensor

Issue Before replacing the rain sensor during a front windshield replacement, contact:

Description: FCA Redacted Content

If no response in 15 minutes, proceed with repair. If there is no visible damage to the original rain sensor it should be transferred to the new windshield using a new gel pad rather than replacing it.
