

17-18-03 - Engine Oil Level

Release date:

6/13/2022

Condition

Applicable Vehicles							
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To		
All (Except Routan, ID.4)	2014-2023	All Gasoline	All	All	All		

Revision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2037201/13	6/13/22	17-18-03	To include model year 2023.			
2037201/12	6/21/21	17-18-03	To include model year 2022.			
2037201/1	7/2/14	V171402	Original publication.			

Technicians may find during PDI that the oil level is below the full mark, but still within the hash marks on the engine oil dip stick.

Technical Background

All Volkswagen gasoline engines are filled to a specific volume before leaving the factory. This level may vary depending on the testing conditions, but will always be within the allowable specification for engine protection.

Production Solution

Not applicable.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



17-18-03 - Engine Oil Level

Release date: 6/13/2022


Service

When checking the engine oil level during PDI, ensure the oil level is within the oil level marks (B range in Figure 1) on the oil dip stick.

When checking the engine oil level, ensure the engine is at operating temperature, park the vehicle on a level surface to help prevent an incorrect oil level reading.

Switch off the engine and wait five minutes for the engine oil to flow back into the oil pan before checking the level.

If the oil level is within the B range, DO NOT add additional oil.





Warranty

Information only.

Required Parts and Tools

Not applicable.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.