

REFERENCE:	Nova Bus Manuals
SECTION:	10: Transmission and Control
RS N°:	MQR 7621-2342 & 7621-2471
EFFECTIVE IN PROD.:	N/A

APPLICATION DEADLINE: N/A

SUBJECT:	Transmission.
JUSTIFICATION:	(MQR-2342) Fix ignition signal issue between TCU and shift selector, code130. (MQR-2471) ZF Ecolife2 shifting program calibration.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Apply the new version of the program.	Supplier	Supplier	N/A
2	-	-	-	-

MATERIAL

QTY	PART N°	REV.	DESCRIPTION
LEVEL 1			
-	-	-	-
LEVEL 2			
-	-	-	-

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED*	RETAINED
	-	-

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2022JN23	Initial release	Devanand

APPROVED BY:

Jean-Nicolas Fournier

Digitally signed by Jean-Nicolas Fournier
DN: cn=Jean-Nicolas Fournier, o=Nova Bus,
email=jean-nicolas.fournier@volvo.com, c=CA
Date: 2022.06.27 13:06:48 -04'00'

PAGE 1 OF 2

* Software Programming will be done by local ZF service dealer							
CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY	PROGRAM
		FROM	TO	FROM	TO		
Academy Busline - New Jersey	LD60	—	—	L82JXM3752934	L82JXM3752948	15	6070205329_AK0_DS.HEX
Brantford Ontario	LE09	102105	102109	L82J8M3753208	L82JXM3753212	5	6070205965_AO1_HS.HEX
Cold Lake Alberta	LE02	5017	5017	L82J9M3753122	L82J9M3753122	1	6070207116_AO1_GS.HEX
Durham Region Transit Ontario - Metrolinx	LD91	7104	7117	L82J0M3753056	L82J5M3753070	14	6070207116_AO1_GS.HEX
Durham Region Transit Ontario - metrolinx	LE20	7118	7118	L82J2M3753334	L82J2M3753334	1	6070207116_AO1_GS.HEX
Whitehorse - Yukon	LD50	—	—	L82J5M3752999	L82J6M3753000	2	6070205329_AK0_DS.HEX

**NOTE**

Software Programming will be done by local ZF service dealer

