

CAMPAIGN LAUNCH STATUS

N682 SERVICE ACTION – VEHICLE EMISSION LABEL



| CUSTOMER SATISFACTION SERVICE ACTION | N605 INCORRECT VEHICLE EMISSION LABEL |
|--------------------------------------|---|
| AFFECTED MODELS | 22 MY Defender |
| VOLUME AFFECTED | USA 3256 CAN 244 |
| REPAIR | Certain 21MY Defender Vehicles have been built with an under hood emission label with incorrect vehicle data. At the next service visit, retailers are to remove the under hood label and install a new, correct label. |
| REPAIR TIME | 0.2 hrs |
| CAMPAIGN LAUNCH | May 25 th ,2022 |
| Notes | Retailers are to order replacement labels following normal parts processes. Labels are not VIN specific. |



PRINTED COPIES ARE UNCONTROLLED