

CAMPAIGN LAUNCH STATUS

N682 SERVICE ACTION – VEHICLE EMISSION LABEL



CUSTOMER SATISFACTION SERVICE ACTION	N605 INCORRECT VEHICLE EMISSION LABEL
AFFECTED MODELS	22 MY Defender
VOLUME AFFECTED	USA 3256 CAN 244
REPAIR	Certain 21MY Defender Vehicles have been built with an under hood emission label with incorrect vehicle data. At the next service visit, retailers are to remove the under hood label and install a new, correct label.
REPAIR TIME	0.2 hrs
CAMPAIGN LAUNCH	May 25 th ,2022
Notes	Retailers are to order replacement labels following normal parts processes. Labels are not VIN specific.



PRINTED COPIES ARE UNCONTROLLED