

CAMPAIGN LAUNCH STATUS

N640 SERVICE ACTION - DIESEL ENGINE PCM CALIBRATION



| SERVICE ACTION N640 – 16-21 MY MODELS WITH 3.0L AND 2.0L Diesel engines | |
|---|--|
| AFFECTED MODEL | 16-21MY Range Rover , Range Rover Sport; 17-21MY Discovery, 18-19MY Velar |
| VOLUME AFFECTED | USA 25,011, CAN 9,341 |
| ISSUE/REPAIR | A Powertrain Control Module (PCM) calibration update is required on specific diesel engine vehicles to correct a software error that can affect the operation of the Exhaust Gas Recirculation (EGR) System. |
| REPAIR TIME | 0.2hrs +DIDO |
| CAMPAIGN LAUNCHED | Launched May 13 th , 2022 Suspended May 26 th , 2022 |
| Notes | June 6 th - Campaign is now closed and will not be re-issued. |

CANCELLED

