



Service Bulletin

Bulletin No.: 22-NA-042

Date: February, 2022

INFORMATION

Subject: Information on Camaro ZL1 10-Speed MGL Automatic Transmission Fluid Level Setting for the Track

This bulletin replaces PIP5506. Please discard PIP5506.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: (Automatic) |
|-----------|------------|-------------|------|------|----|------------|------------------------------|
| | | from | to | from | to | | |
| Chevrolet | Camaro ZL1 | 2017 | 2022 | — | — | 6.2L (LT4) | MGL, MI1 |

| | |
|----------------------------|--|
| Involved Region or Country | North America, Middle East, Chile, Ecuador, Paraguay, Peru, Japan, GM Korea Company, Thailand |
| Additional RPO/s: | ZL1: MERCHANDISED PKG-SPECIAL PERFORMANCE |
| Condition | The Chevrolet Camaro High Performance Owner Manual Supplement indicates that the Camaro ZL1 has a 10-speed transmission and the fluid level should be set to the track specific oil level. |
| Cause | The Chevrolet Camaro High Performance Owner Manual Supplement is incorrect. |
| Information | The 10-speed transmission used in the Camaro ZL1 does not require a track specific oil level. The fluid should be set following procedures outlined in Service Information (SI). |

| | |
|----------|----------------------------|
| Version | 1 |
| Modified | Released February 17, 2022 |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**