

64 Exterior glass cleaning

64 22 85 2020552/11 July 5, 2022. Supersedes Technical Service Bulletin Group 64 number 21-80 dated May 6, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Models	2010 – 2023	All	Not Applicable

Condition

REVISION HISTORY				
Revision	Date	Purpose		
11	-	Revised header (Added model years)		
10	05/06/2021	Revised header (Added model years and new models)		
9	05/08/2020	Revised header (Added model years)		

Customer states:

The windshield is streaked, has a snakeskin appearance, or its surface feels rough.

Technical Background

Residue from industrial fallout as well as normal road dirt and grime may accumulate on the windshield.

Page 1 of 6

^{© 2022} Audi of America, Inc.



Production Solution

Not applicable.

Service

Tip: This procedure must be performed and verified before a wiper blade replacement. All Warranty claims will be rejected for wiper blade replacement if a defect is not found.

- 1. Wash and dry all affected exterior glass surfaces.
- Place wipers in the service position (Figure 1).



Figure 1. Windshield wipers in the service position.

 Using household glass cleaner (such as Windex[®] or 3M[™] Glass Cleaner), clean residue from wiper blades (Figure 2).





Tip: Do not use Figure 2. Cleaning wiper blades.

Page 2 of 6

© 2022 Audi of America, Inc.



Polishing Compound to clean the wiper blades.

 Shake bottle of 3M[™] Glass Polishing Compound (Figure 3) to mix product evenly.



Figure 3. 3M[™] Glass Polishing Compound.

 Apply cleaner directly to the outside of the windshield on both driver and passenger sides (Figure 4).



Figure 4. Cleaner applied to the windshield.

Page 3 of 6

© 2022 Audi of America, Inc.

 Use a clean, dry microfiber cloth (such as 3M[™] Microfiber Detail Cloth - Yellow) (Figure 5) to vigorously clean windshield with long, horizontal strokes (Figure 6).

> Try to avoid applying the product to the window trim.



Figure 5. Detailing cloths.



Figure 6. Using horizontal strokes to clean the windshield.

7. Allow drying time until a fine film layer (haze) forms.

Page 4 of 6

© 2022 Audi of America, Inc.

Tip: Drying time is based on ambient temperatures. Temperatures of 60°F (15°C) or lower can extend drying time.

 Use a garden hose to rinse the windshield. Also, rinse any product that was inadvertently applied to the trim (Figure 7).



Figure 7. Rinsing the windshield.




Figure 8. Drying the windshield.

10. With warm water, wet and ring out microfiber cloth. Wipe off any residue that made contact with trim or rubber.

Page 5 of 6

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

9. With a clean, dry microfiber cloth, dry and buff glass to a clean shine (Figure 8).

^{© 2022} Audi of America, Inc.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.				
Part Number	Part Description	Quantity		
60150	3M [™] Glass Polishing Compound (Please order through Audi Top Service Supplies & Touch Up Paint eStore)	01		
39016	3M [™] Microfiber Detail Cloth – Yellow (Please order through Audi Top Service Supplies & Touch Up Paint eStore)	01		

Additional Information

All parts and service references provided in this TSB (**2020552**) are subject to change and/or removal. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Page 6 of 6

^{© 2022} Audi of America, Inc.