



## EMISSIONS RECALL

### 2022 CRF450RL - ECU Inspection

#### BACKGROUND

Honda is launching a EMISSIONS RECALL on CERTAIN 2022 CRF450RL motorcycles to inspect the ECU. The affected units may have had an incorrect ECU installed at the factory. A motorcycle with an incorrect ECU may exhibit drivability issues and is not within emissions certification compliance.

#### AFFECTED UNITS

As of July 18, 2022, YOU MUST NOT SELL CERTAIN NEW or USED 2022 CRF450RL motorcycles until they are repaired according to this Service Bulletin.

- To search for applicable recalls on a specific unit, you MUST use *Unit Information on iN*, available July 19, 2022.
- To manage your affected inventory, refer to *eResponsibility Report on iN*, available July 20, 2022.

#### CUSTOMER NOTIFICATION

American Honda intends to mail customer letter to all owners of affected 2022 CRF450RL motorcycles in September 2022. Customers will be informed that their motorcycle may be affected by a emissions related defect and will be advised to make an appointment with an authorized Honda dealer for repair.

#### PARTS INFORMATION

Parts will be available in early August 2022. All parts needed for this repair are under *TechLine* control. You MUST contact *TechLine* to have these parts released.

#### REPAIR PROCEDURE

The complete Service Bulletin with repair procedure, parts information, as well as warranty claim information is expected to be available on *iN* by the end of business Tuesday, July 26, 2022.

#### DEALER REPAIR RESPONSIBILITY

- Safety Recall repairs must be performed by a qualified technician.
- Installing the remedy parts exactly as shown in Repair Procedure instructions is critical for the recall remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this safety recall was properly performed.