

<b>Subject:</b>  PAINT PEELING FROM THE FRONT BUMPER OR BUMPER TRIM	Service Alert No.: SA-047/22
	Last Issued : 07/27/2022


## BULLETIN NOTES

### APPLICABLE MODEL(S)/VINS

2023 CX-50

## DESCRIPTION

Some vehicles may exhibit paint peeling on the front bumper as shown in the photo.



## REPAIR PROCEDURE

Replace the front bumper garnish "C".

## PARTS INFORMATION

Parts Number	Description	Qty.	Notes
VA40-50-1T4	Garnish (C), Bumper	1	Guard Material Color
VA50-50-1T4	Garnish (C), Bumper	1	Silver Color

**NOTE:** If unsure of the color, look up the part in the GEPC (Global Electronic Parts Catalog) using the VIN.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.