

# WMA3 Workshop campaign - Replacing wheel bearing housing

---

## WMA3 Workshop campaign - Replacing wheel bearing housing

ID Number	WMA3
Models	911 (992)
Model Years	2020-2021
VIN list	Attached
Number of Affected VINs	774
Issue Description	<p>There is a possibility that one or more taper bushings were not pressed into the wheel bearing housing reliably.</p> <p>A deviation during the pressing-in process may have caused chips to form between the adjoining parts. Under extreme driving conditions, these chips could reduce the remaining life span of the affected components.</p>
What Dealers should do	<p>Please arrange for the repair to be carried out on affected vehicles as soon as possible.</p> <p><b>The repair is available as of the time of this posting.</b></p>
TI Number	<a href="#">No. 11-21</a>

## Parts required

### Replacing front left wheel bearing housing - Vehicles with campaign scope 1, 4, 7, 10, 12 and 15

- Relevant for 911 Carrera (992), 911 Carrera S (992), 911 Carrera 4S (992), 911 Carrera 4 (992), 911 Carrera GTS (992)

Part No.	Designation	Quantity/vehicle	Parts return*
----------	-------------	------------------	---------------

---

WMA3 Workshop campaign - Replacing wheel bearing housing

992407245 Y	Left pivot bearing (I-no. 0N1)	1 unit	No
or (depending on scope)			
992407245AY	Left pivot bearing (I-no. 0N5)	1 unit	No
9P1407621	Angular-contact ball bearing	1 unit	No
WHT007021	Hexagon nut	2 units	No
PAF909664	Hexagon collar nut (without PDCC)	2 units	No
or (depending on scope)			
PAF008758	Hexagon flange bolt (with PDCC, I-no. 1P7)	2 units	No
PAF908088	Hexagon collar nut	2 units	No
PAF100829	Hexagon-head bolt (with washer assembly)	3 units	No
PAF008742	Hexagon-head bolt	1 unit	No
N 10456004	Internal hexagon round countersunk screw	2 units	No
9A700758500	Cheese head bolt (I-no. 1LR, 1LS)	2 units	No
or (depending on scope)			
WHT008186	Cheese head bolt (I-no. 1LQ, 1LX, 1LZ)	2 units	No

## Replacing front right wheel bearing housing - Vehicles with campaign scope 2, 5, 8, 13 and 16

- Relevant for 911 Carrera (992), 911 Carrera S (992), 911 Carrera 4S (992), 911 Carrera 4 (992), 911 Carrera GTS (992)

Part No.	Designation	Quantity/vehicle	Parts return*
992407246Y	Right pivot bearing (I-no. 0N1)	1 unit	No
or (depending on scope)			
992407246AY	Right pivot bearing (I-no. 0N5)	1 unit	No
9P1407621	Angular-contact ball bearing	1 unit	No
WHT007021	Hexagon nut	2 units	No

WMA3 Workshop campaign - Replacing wheel bearing housing

PAF909664	Hexagon collar nut (without PDCC)	2 units	No
or (depending on scope)			
PAF008758	Hexagon flange bolt (with PDCC, I-no. 1P7)	2 units	No
PAF908088	Hexagon collar nut	2 units	No
PAF100829	Hexagon-head bolt	3 units	No
PAF008742	Hexagon-head bolt	1 unit	No
N 10456004	Internal hexagon round countersunk screw	2 units	No
9A700758500	Cheese head bolt (I-no. 1LR, 1LS)	2 units	No
or (depending on scope)			
WHT008186	Cheese head bolt (I-no. 1LQ, 1LX, 1LZ)	2 units	No

## Replacing front left and right wheel bearing housing - Vehicles with campaign scope 3, 6, 9, 11, 14 and 17

- Relevant for 911 Carrera (992), 911 Carrera S (992), 911 Carrera 4S (992), 911 Carrera 4 (992), 911 Carrera GTS (992)

Part No.	Designation	Quantity/vehicle	Parts return*
992407245 Y	Left pivot bearing (I-no. 0N1)	1 unit	No
or (depending on scope)			
992407245AY	Left pivot bearing (I-no. 0N5)	1 unit	No
992407246Y	Right pivot bearing (I-no. 0N1)	1 unit	No
or (depending on scope)			
992407246AY	Right pivot bearing (I-no. 0N5)	1 unit	No
9P1407621	Angular-contact ball bearing	2 units	No
WHT007021	Hexagon nut	4 units	No
PAF909664	Hexagon collar nut (without PDCC)	4 units	No
or (depending on scope)			

WMA3 Workshop campaign - Replacing wheel bearing housing

PAF008758	Hexagon flange bolt (with PDCC, I-no. 1P7)	4 units	No
PAF908088	Hexagon collar nut	4 units	No
PAF100829	Hexagon-head bolt	6 units	No
PAF008742	Hexagon-head bolt	2 units	No
N 10456004	Internal hexagon round countersunk screw	4 units	No
9A700758500	Cheese head bolt (I-no. 1LR, 1LS)	4 units	No
or (depending on scope)			
WHT008186	Cheese head bolt (I-no. 1LQ, 1LX, 1LZ)	4 units	No

## Replacing front left and right wheel bearing housing - Vehicles with campaign scope 18 and 19

- Relevant for 911 Turbo (992), 911 Turbo S (992)

Part No.	Designation	Quantity/vehicle	Parts return*
992407245CY	Left pivot bearing	1 unit	No
992407246CY	Right pivot bearing	1 unit	No
9P1407621	Angular-contact ball bearing	2 units	No
WHT007021	Hexagon nut	4 units	No
PAF909664	Hexagon collar nut (without PDCC)	4 units	No
or (depending on scope)			
PAF008758	Hexagon flange bolt (with PDCC, I-no. 1P7)	4 units	No
PAF908088	Hexagon collar nut	4 units	No
PAF100829	Hexagon-head bolt	6 units	No
WHT006151	Hexagon collar nut	2 units	No
PAF008742	Hexagon-head bolt	2 units	No
N 10456004	Internal hexagon round countersunk screw	4 units	No
WHT008186	Cheese head bolt (I-no. 1LQ, 1LX)	4 units	No

\* The parts must be stored until such a time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode

is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

## Required materials

Usually already available, only order if additional materials are required.

Part No.	Designation - Location	Quantity/vehicle
00004302000	Mounting paste - Brake disc	100g tube (0.05 each = approx. 5 g)
00004320683	Lubricant - Speed sensor	80g tube (0.03 each = approx. 2 g)

## Warranty processing

Validity:

This workshop campaign will be carried out up to 11/18/2026 and will be closed on that date.

Please note that warranty claims can only be processed before this date.

Scope 1 - 19:

Please note that just one campaign scope is assigned to each vehicle.

The relevant campaign scope assigned to a vehicle can be viewed using the vehicle identification number in the "Vehicle information" display in PCSS.

- Scopes 1 - 17: Relevant for 911 Carrera (992) / 911 Carrera S (992) / 911 Carrera 4S (992) / 911 Carrera 4 Coupe (992) / 911 Carrera GTS Coupe (992) / 911 Carrera 4 GTS Coupe (992) / 911 Targa 4 (992) / 911 Targa 4S (992) / 911 Targa 4 GTS (992)
- Scopes 18 - 19: Relevant for 911 Turbo (992) / 911 Turbo S (992)

Damage code	WMA3 66 000
Repair code	2
Working time	415 - 581 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

## Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.