

WNA6 Workshop campaign – Reworking fastening bolts on the underbody

WNA6 Workshop campaign - Reworking fastening bolts on the underbody

ID Number	WNA6
Models	Cayenne (9YA/9YB)
Model Years	2022
VIN List	Attached
Number of Affected VINs	271
Issue Description	<p>Due to an error during the production process, fastening bolts that do not meet the required specifications were installed on the affected vehicles.</p> <p>In the event of unfavorable tolerances in the body, there is a possibility of contact occurring between the fuel tank and fastening bolts while driving.</p> <p>To prevent this from happening, the fastening bolts have to be reworked. The fuel tank will also need to be checked for damage and replaced if necessary.</p>
What Dealers should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available. Parts can be ordered as needed via PPL with no PRMS ticket.</p>
Customer Notification	Will be released at a later date
TI Number	No. 22-22

Required parts and materials

Part No.	Designation	Quantity/vehicle	Parts return**
WNA60000001*	Expendable items	1 ea.*	No

WNA6 Workshop campaign – Reworking fastening bolts on the underbody

Additional parts and materials required, only if floor pan is damaged:

PAB804535	Seal	Up to 2 ea. (only if required)	No
-----------	------	-----------------------------------	----

* For guarantee invoicing for Part No. WNA60000001, enter "expendable items" designation as a **third party part**, amount \$0.63.

**The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Warranty processing

Scope 1:

Damage Code	WNA6 66 000
Repair Code	1
Working time	133 TUs

Scope 2:

Damage Code	WNA6 66 000
Repair Code	1
Working time	136 TUs

Please enter the campaign that was carried out in the Guarantee and Maintenance booklet for the vehicle.

Customer transport

If requested, transport for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.