

WNB2 Workshop campaign – Replacing Front Grille Trim

WNB2 Workshop campaign - Replacing Front Grille Trim

ID Number	WNB2
Models	Macan (95B)
Model Years	2022
VIN List	Attached
Number of Affected VINs	35
Issue Description	<p>Due to an allocation error in the parts list, the front grille trim piece in vehicle color or matte black was installed instead of the ordered piece in high-gloss black on the affected vehicles.</p> <p>To ensure customer satisfaction, the front grille trim on the affected vehicles must be replaced with a trim in the high-gloss black version.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available. Parts can be ordered via PPL with no PRMS ticket needed.</p>
TI Number	No. 35-22

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
95B827555	Trim (grille, prime-coated)	1 ea.	no
WNB20000001**	Expendable items	1 ea. (for warranty invoicing only)	-

*The parts must be stored until such time as the related guarantee or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can directly be scrapped.

**For warranty processing, enter the Part No. WNB20000001 with the designation "consumables" as an additional part in the warranty claim; maximum cost: \$37.50.

Warranty processing

Validity:

This workshop campaign will be carried out up to March 10, 2027 and will be closed on that date.

Please note that warranty claims can only be processed before this date.

Scope 1: Replacing skid plate

All work required for replacing the skid plate was carried out fully by the Porsche Dealer.

Damage Code	WMB2 66 000
Repair Code	2
Labour time	349 TU

Scope 2: Replacing skid plate

All work required for replacing the skid plate was carried out fully by the Porsche Dealer

Vehicles with equipment M-no. KA6

Damage Code	WMB2 66 000
Repair Code	2
Labour time	411 TUs*

Scope 3: Replacing skid plate

The skid plate was painted by an external service provider.

Damage Code	WMB2 66 000
Repair Code	2
Labour time	169 TUs*

Scope 4: Replacing skid plate

The skid plate was painted by an external service provider.

Vehicles with equipment M-no. KA6

Damage Code	WMB2 66 000
Repair Code	2
Labour time	231 TUs*

* The maximum amount that will be paid as sublet labor time is the amount corresponding to the specified labor time based on the individual charging rate under warranty of the respective Porsche dealer. Please include a copy of the invoice for external services with the warranty claim.

Please enter the campaign that was carried out in the Guarantee and Maintenance booklet for the vehicle.

Customer Mobility

If requested, transport for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.