

Fan Drive Belt, Replacement

M-263-003

(May 2009)

Valid for

All Mack trucks US07 with an MP7 engine.

Case description

When replacing a fan belt, backing material from the original belt may be found deposited on the pulley. If deposits are discovered the pulley needs to be cleaned with a wire brush or rag soaked in solvent (isopropyl or similar solution) to remove deposits from pulley before installing a new belt.

Repair



Danger


Do not attempt to repair or service this vehicle without having sufficient training, the correct service literature and the proper tools. Failure to follow this could make the vehicle unsafe and lead to serious personal injury or death.



Caution

Possible damage to electronic components. Turn the vehicle ignition switch OFF before disconnecting or connecting any electronic components. Failure to de-energize circuits may result in permanent damage to electronic components.

1. Remove fan belt.
2. Check pulley for backing material deposits. Clean pulley if needed.
3. Install new fan belt.



Warranty information

Reimbursement

This Repair may be eligible for reimbursement if a product failure was experienced within the time and mileage limits of the applicable warranty coverage. Reimbursement is obtained via normal claim handling process.

Claim Type (used only when uploading from the Dealer Bus. Sys.)	01
Labour Code	
Primary Labour Code	2154G-19-45 0.3 hr.
Causal Part	20887407

Issued by

Technical Service

Mack Trucks, Inc. engages in a continuous program of testing and evaluating to provide the best possible product. Mack Trucks, Inc., however, is not committed to, or liable for updating existing chassis.