 HYUNDAI Technical Service Bulletin	GROUP CAMPAIGN	NUMBER 22-01-069H
	DATE AUGUST, 2022	MODEL(S) PALISADE (LX2)
SUBJECT: TRAILER TOW HITCH HARNESS FUSE REMOVAL (CAMPAIGN P31)		

★ IMPORTANT

***** Retailed Vehicles *****

Dealers must perform this Service Campaign whenever an affected vehicle is in the shop for any maintenance or repair.

Access the “Vehicle Information” screen (VIS) via WebDCS to identify open campaigns.

Description: This bulletin provides the procedure to remove the 40A fuse as an interim action relating to Recall 235 (TSB 22-01-070H or latest version) for vehicles equipped with a Genuine Hyundai Accessory trailer tow hitch and wire harness installed.

STUI



This TSB includes STUI picture(s) as a requirement when applicable. Where indicated, please include a copy of the RO or last 6 digits of the VIN and date of repair on a piece of paper. Ensure the VIN and date of repair are clearly visible. Finally, please ensure all captured pictures are completed according to the steps in this TSB and uploaded to STUI. **All claims submitted that have illegible, incomplete, missing, or incorrect picture(s) are subject to debit.**

Applicable Vehicles: Certain 2020 - 2022 MY Palisade (LX2)



Circulate To: General Manager, Service Manager, Sales Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Warranty Information:

MODEL	OP. CODE	OPERATION	OP. TIME	CAUSAL PART	NATURE	CAUSE
PALISADE (LX2)	P31HITCH	TRAILER TOW HITCH FUSE REMOVAL	0.2 M/H	S8F67-AC401	I11	ZZ3

NOTE 1: This service procedure is only applicable for retailed vehicles that have a Genuine Hyundai Accessory trailer tow hitch and wire harness installed.

NOTE 2: Submit Claim on Campaign Claim Entry Screen.

NOTE 3: If the trailer tow hitch fuse is removed, claim must include a STUI picture of the engine fuse box with 40A fuse removed clearly visible along with a piece of paper displaying the last 6 digits of the VIN and date of the repair. **If not included, claim will be subject to debit.**


Service Procedure:

1. Confirm the vehicle is equipped with the Genuine Hyundai Accessory trailer tow hitch and wire harness installed.



2. Open the hood and locate the fuse box in the engine bay.

Remove the "TRAILER" 40A fuse.



SUBJECT:


**TRAILER TOW HITCH HARNESS FUSE REMOVAL
(CAMPAIGN P31)**

3. Write the last six digits of the VIN and date of repair onto a piece of paper and place it near the engine bay fuse box.

STUI



Using STUI, take a picture of the engine fuse box with the “TRAILER” 40A fuse removed. Upload the photo to STUI.



4. Procedure complete.

This is an interim action relating to Recall 235. The trailer lights will be rendered inoperative until the final Recall remedy has been implemented.

Further instructions will be provided when a remedy is available.