

**WLD1 - Supplying Wheel Spacer (Workshop Campaign)**

Vehicle Type: **911 GT2 RS (991)/911 GT3 RS (991)**

Model Year: **As of 2016 up to 2019**

Equipment: Spare wheel (I-no. 447)

Subject: **Spacer**

Information: In the event of a flat tire, the spare wheel supplied with the vehicle must only be installed on the front axle. If tire damage occurs to a wheel on the rear axle, the relevant front wheel must first be installed on the rear axle and then the spare wheel on the front axle.

**A wheel spacer is required in order to install the front wheel on the rear axle. This wheel spacer was not assigned to the affected vehicles due to an incorrect parts list.**

Remedial Action: Place the wheel spacer in the vehicle to ensure that the front wheel can be installed on the rear axle in the event of a flat tire.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information). This campaign affects 1 vehicle in North America.

Part Info:	Part No.	Designation	Qty.
	99736160593	⇒ Spacer	1 ea.




**Unsecured load**

- **An unsecured, incorrectly secured or incorrectly positioned spare-wheel bag can slip out of place and endanger occupants when braking, changing direction or in the event of an accident.**
- ⇒ **Never transport the spare wheel bag in the passenger compartment unsecured.**
- ⇒ **Always stow the wheel spacer in the spare wheel bag secured on the passenger seat.**

Work Procedure: 1 Remove the spare wheel together with the holder from the passenger seat and open the spare wheel bag.

- 2 Stow the wheel spacer ⇒ *Placing the wheel spacer in the vehicle -1-* in the bag ⇒ *Placing the wheel spacer in the vehicle -2-* as shown in the illustration behind the tool bag on the inside of the rim of the spare wheel ⇒ *Placing the wheel spacer in the vehicle -3-*.
- 3 After placing the wheel spacer in the vehicle, close the spare wheel bag and strap the spare wheel with the holder to the passenger seat.
- 4 Enter the campaign in the Warranty and Maintenance booklet.



*Placing the wheel spacer in the vehicle*

Scope:

**Working time:**

Supply spacer

Labor time: **10 TU**

**Parts required:**

99736160593 Spacer

1 ea.

⇒ **Damage Code WLD1 066 000 1**

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.