

## GPOP - Issue Review System

**Part Number:** 68441925A\$, 68438534A\$, 68427337A\$, 68354732A\$

**Part Description:** Windshield

**Issue Description:** Before replacing the windshield on 2022MY Wagoneer/Grand Wagoneer vehicles for stress cracking, please contact FCA Redacted Content. For vehicles with obvious damage (impact from stone chip, accident, etc.), simply proceed with the replacement, there is no need to call.

For stress crack vehicles, upon calling if no response in 15 minutes, proceed with repair. Please send pictures of the issue to FCA Redacted Content